



Bundles should be no higher than 15 forms high or 48" in width



STEEL PLY RETURN SPECIFICATIONS

- Contact your salesman or Form Tech branch for a list of the equipment that you have on rent.
- Forms are to be cleaned and free of dirt and concrete build up.
- Forms are to be sprayed with a thin coat of form release agent.
- Bottom forms are to be placed with the wood face down.
- Remaining forms are to be placed with the wood face up.
- 24" panels – bundle 2 forms wide x 15 forms high (30 pack).
- Wood face fillers – bundle best you can, maximum 15 forms high x 48" wide.
- Steel fillers, corners, etc. – bundle best you can, maximum 40" high x 48" wide.
- Do not mix forms of different heights (lengths) in the same bundles.
- All bundles of forms are to be banded for safe transporting.
- Skids or dunnage is to be placed under ALL bundles of formwork when loading on trailer, for ease in loading and unloading.
- Hardware is to be separated and placed in bags, pails, crates, bins or other. When at all possible, use same packaging as items were shipped in.

All items MUST be loaded on the trailer for side unloading at Form Tech's yard.

ADDITIONAL CHARGES

- Forms returned dirty will result in a cleaning charge.
- Repairable holes in wood face will be repaired and billed accordingly.
- Multiple holes per form and/or damaged wood faces will result in the wood face being replaced and billed accordingly.
- Any items returned that have repairable damage or if they are damaged beyond repair, will be billed accordingly.

IF YOU HAVE ANY QUESTIONS OR CONCERNS REGARDING THE PACKAGING OF FORMS AND HARDWARE FOR RETURNING, PLEASE CALL YOUR FORM TECH LOCATION. WE WILL BE MORE THAN HAPPY TO ASSIST YOU TO MAKE THE RETURN PROCESS AS SMOOTH AS POSSIBLE FOR ALL PARTIES INVOLVED